It has been reported by several Teams that there is a problem related to the balls either passing through the Stationary Citadel Hill Nets at first contact with the net or falling out of the bottom of the net as a quantity of balls accumulates in the net and stretches the mesh.

## Carl Monfils, EAO

Enseignant en éducation technologique 9-12 Coordonnateur de la concentration design Collège catholique Mer Bleue 6401 Renaud Rd, K1W0H8 (613) 744-4022 ex. 41856



Carl Monfils has suggested and tested a solution to this problem.

Carl's solution will be used at the Ontario Competition.

The Laundry Net required for implementing Carl's solution is available at Home Depot.

https://www.homedepot.ca/produit/whitmor-panier-a-linge-avec-doublure-easycare/1001070338







